

## STICKY CLEAN MATS

Sticky Clean Mats are effective to remove the dust & contamination of the shoes before entering the clean working place, such as in semiconductor electronic manufacturing, hospital and operation room, pharmaceutical and biological manufacturing, medical device manufacturing, photographic equipment manufacturing.

- Non-polluting, uniform thickness and width, adequate adhesiveness along its full length, high durability.
- Micro-film prevents accident by cart or human.
- Numbered corner tap for easy identification.
- No adhesive residue on shoe's sole.
- Available in blue, white, clear, gray, green colors, and in sanitized adhesive film which suppresses microbial proliferation.



ITEM #	SIZE	Pack Size	COLOR
AC-ADH-324	18" x 45"	One carton including 10 packs of 30 layers	WHITE
AC-ADH-325	24" x 45"	One carton including 10 packs of 30 layers	WHITE
AC-ADH-326	24" X 45"	One carton including 10 packs of 30 layers	GRAY
AC-ADH-324-4	18" x 45"	One carton including 4 packs of 30 layers	WHITE
AC-ADH-325-4	24" x 45"	One carton including 4 packs of 30 layers	WHITE
AC-ADH-326-4	24" X 45"	One carton including 4 packs of 30 layers	GRAY

Technical Data		Specifications	
		Standard	Sanitized
Adhesive Strength(g)	Normal	200±50	←
	High	400±50	←
Tensile Strength	Width(mg/mm <sup>2</sup> )	>1.5	←
	Length(/kgmm <sup>2</sup> )	>1.5	←
Chemical resistance	Sodium Hydroxide	Good	←
	Methanol	Good	←
	Nitric Acid	Fair	←
	Sulfuric acid	Fair	←
	Toluene	Poor	←
Bacterial Inhibition (pcs. after 24hrs).	E-Coil (initial : 7.6×10 <sup>5</sup> )	5.3×10 <sup>5</sup>	4.0×10 <sup>3</sup>
	S.aureus(initial : 7.0×10 <sup>5</sup> )	4.2×10 <sup>5</sup>	8.3×10 <sup>3</sup>
Dimension(mm)	Width	±3	←
	Thickness	0.055±0.005	←